



Electronic timing setting

CT1167 as well as all associated kits for Audi, Seat, Skoda and VW. Various 1.0-1.6L TSI, EA211 models with electronic camshaft adjustment.

Problem

When fitting the timing belt, the bolts for the camshaft adjustment (Fig. 1) must be loosened. After belt replacement the timing and lead angle for the electronic camshaft adjustment are not set accurately enough with the mechanical locking tools.

Cause

A new combustion process means that the intake valves can be closed very early on this engine while the intake stroke is still in progress. Loosening the bolts for the camshaft adjustment can cause the timing to be set incorrectly or inaccurately, which has a major effect on mixture preparation.

Solution

The basic setting needs to be programmed and adjusted electronically using testing tool VAS 611 007 (Fig. 2).

The VAS 611 007 tool is capable of setting the camshaft angle so that it is accurate to one tenth of a degree **(Fig. 3)**. Additional time allowance for the setting work: approx. 2.5 h.

There are two different adapters for the tool (Fig. 4):

- > Tool VAS 611 007/8 for three- and four-cylinder TSI units without Active Cylinder Technology
- > Tool VAS 611 007/4 for four-cylinder TSI units with Active Cylinder Technology

Fig.1



Fig.2



Fig.3




Fig.4



Images: TKR Spezialwerkzeuge GmbH

ContiTech Antriebssysteme GmbH

Philipsbornstraße 1, D-30165 Hannover Techn. Hotline +49 (0)511 938 -5178 aam@continental.com www.continental-engineparts.com The content of this publication is not legally binding and is provided for information purposes only. ContiTech AG does not assume any liability in conjunction herewith. To the extent permitted by law, no liability is assumed for any direct, indirect, incidental, consequential or punitive damages arising out of the use of this publication. © 2023 by ContiTech AG, Hanover. All rights reserved.