



Ford Mondeo III Model year from 2000 to 2004 All vehicles with xenon light

Failure of the xenon headlight

If there are complaints about the above-mentioned fault, a defective ignition module could be the cause. Failure is sporadic, but is found with increasing frequency when cold-starting a vehicle. In this case, the ignition module must be replaced. Therefore, the manufacturer offers a conversion kit with a new generation of ignition modules.

Proceed as follows:

- Disconnect the battery.
- Remove the headlight and unscrew the rear headlight cover. (See Bulletin "Ford Mondeo replacement of the light source").
- Remove the contact plug from the xenon bulb, and unscrew the old ignition module (see Fig. 1) from the headlight.
- Loosen the fastening ring of the xenon bulb, and afterwards refasten the bulb with the modified ring.
- Plug the new ignition module (see Fig. 2, Item 1) onto the xenon bulb, and turn it to the right to fasten it.
- Connect the adapter cable (see Fig. 2, Item 2) to the power supply cable of the old ignition module.
- After that, plug the contact plug (see Fig. 2, Item 3) into the new ignition module.
- Refit the headlight cover and all other removed parts in reverse order.

Check the system for perfect function.

Adjust the headlight with the help of a diagnostic tester (take a readout of the fault code, basic adjustment of



the headlight range adjustment, etc.).

Fig. 1



Fig. 2

