

# Trouble codes - lost in translation

An older model Mercedes that ran well failed the NCT on excessive emissions. The trouble code was less than straight forward in its attempt to explain the cause of the fault. A bit of good diagnostics and testing found the problem.

A 1996 Mercedes E36 AMG was brought into the workshop after it failed the NCT test. Apart from a few minor niggles, its main failure was that the emissions, both CO and HC, were just a bit too high. As a result of these two readings being high, obviously the lambda was wrong as well.

The car appeared to drive well and was not suffering any major misfire, a 10 minute inspection of the engine bay did not reveal anything untoward. It was now time to see if there were any fault codes stored in the vehicle's engine management ECM. The system fitted to the vehicle was a Bosch Motronic M 3.4.2, and although this vehicle is over 14 years old, the on-board diagnostic system seemed quite advanced for its years. The fault code retrieved was somewhat convoluted "dwell angle end of control stop reached". This is a prime example of an engine management system trying to describe the fault in just a few words. My favourite example of this is on many VW models "Multiplicative mixture correction at end of control stop." Just try explaining that to the young man, when his VW Golf has failed it's NCT.


Back to our Mercedes, having established our fault code, it was now necessary to drill down further to understand the code definition. The engine management system on this particular vehicle, given its age, controls both fuelling and ignition in one. So the dwell angle, or the amount of time the coils are being charged under the control of the engine ECM, had reached its limits and the engine ECM could not increase this time any further. This engine management system utilises three double ended coils which are mounted directly between the camshafts, leaving very limited access for testing the secondary side of the coils, so instead we focused on the primary side of the coils

As you can see in figure 1, there was a textbook primary wave pattern on two of the coils. Just prior to the firing line you can see the current limiting hump, indicating that the coil had become fully charged, and that the engine ECM had in fact stopped charging this particular coil.

In figure 2, circumstances are much different. You can see straight away that

there is no current limiting hump. In fact, 2 ms into the coil charging time, the engine ECM stopped charging this coil, or what was more likely happening was that the insulation on this coil was breaking down. The breakdown of the coil insulation created an earth path, and prevented this one coil from charging properly. Also note that the burn time was only half the time of the other two coils, and that there are no coil oscillations indicating a very discharged coil. The faulty coil was replaced, the code was cleared and the emissions returned to normal.

Although this particular fault was on a 15 year old Mercedes, I'm sure many other vehicles will be suffering similar faults. However, we expect the engine management system can recognize these faults and then give a text description that we can actually comprehend and then work with. I'm sure that as cars get ever more complicated, the text description of the fault code will follow the same pattern.



Two of the coils in the Mercedes were perfect, as can be seen in this textbook coil primary trace.




Figure 2. One of the coils in the Mercedes was obviously faulty, the result of a short to earth through the coil insulation.