


## Want to test the chain drive of Mercedes-Benz models with M271 engine (EVO)? No problem!

Rattling noises may be heard after a cold start in models with M271 engine (EVO). This may be caused by wear of the chain drive, sprockets, or elongation of the timing chain. This can lead to incorrect timings and, in the worst case, to engine damage.

It is advisable to check the chain drive if the problem described above occurs. However, this is a very time-consuming process.

### febi bilstein has the solution!



The measuring chain tensioner has a graduated scale from 55 to 85. If all chain drive components, e.g. chain tensioner, chain, guide rails and sprockets, are in perfect condition, the measuring chain tensioner should indicate a value of approximately 62.5.

If the measuring chain tensioner indicates a value above 75 (as a continuous line), parts of the chain drive are worn. In this case, examine the chain drive in more detail and replace the appropriate components.



#### Attention!

The measuring chain tensioner must not remain in the engine after testing. It is only a testing tool! Replace chain tensioner febi 40152. The chain tensioner previously fitted must not be reinstalled.

Measuring chain tensioner  
febi no. 40125



Fits:  
Mercedes-Benz models with M271 engine (EVO) and inverted tooth chain  
Repl. no. 271 589 07 63 00

febi no. 40152



Register now for the official febi bilstein newsletter and receive the latest technical information automatically by email! Further information may be obtained at: [www.febi.com](http://www.febi.com)

Simply ask for spare parts by febi bilstein. The complete range can be found at: [www.febi-parts.com](http://www.febi-parts.com)

Ferdinand Bilstein GmbH + Co. KG  
Wilhelmstr. 47 | 58256 Ennepetal | Germany

Tel: +49 2333 911-0

Fax +49 2333 911-444

Email [info@febi.com](mailto:info@febi.com)

febi is a bilstein group brand

[www.febi.com](http://www.febi.com)