



## Different versions of the tensioner pulley V55739, included in the timing belt kits CT1028K3, CT1028WP1, CT1028WP2, CT1028WP3, CT1028WP4 and

**CT1028WP5,** and used in various 1.4 – 2.0l TDI EA180 common-rail engines from Audi/Seat/Škoda/VW

## Note:

The V55739 tensioner pulley supplied may look different from the tensioner pulley fitted in the vehicle. There are two different versions:

Fig. 1: Version 1






Fig. 2: Version 2





## **Solution:**

The two versions of the tensioner pulley can both be used in the designated vehicle models without any problems. Both versions are tensioned by turning them clockwise. The position of the adjustment slot is different.

Version 1: The adjustment slot is at 1 o'clock.

Version 2: The adjustment slot is at 10 o'clock. Once the belt has been fitted, the locking pin must be pulled out. The rest of the tensioning procedure is identical to version 1.

## ContiTech Antriebssysteme GmbH

Philipsbornstraße 1, D-30165 Hannover Techn. Hotline +49 (0)511 938 -5178 aam@continental.com www.continental-engineparts.com

The content of this publication is not legally binding and is provided for information purposes only. ContiTech AG does not assume any liability in conjunction herewith. To the extent permitted by law, no liability is assumed for any direct, indirect, incidental, consequential or punitive damages arising out of the use of this publication. © 2023 by ContiTech AG, Hanover. All rights reserved.