

Cooling



Ford

C Max Mk I, Fiesta IV, Focus Mk I, Focus Mk II,
Focus C Max, Galaxy III, Mondeo IV, S Max,
Courier II, Fiesta Van IV, Transit Connect,
Transit Tourneo Connect 1.8TD

COTB 0015

FWP 1790



It is imperative to use the bolts that are supplied with this water pump due to changes to the thickness of the pump body.

Failure to use the supplied bolts can cause damage to the engine block.

It is essential that care is taken when installing the pump as the bolt protrusion can damage the engine block water jacket if they are not located in the correct position.

FIRST LINE 
THE ALL MAKES SPECIALIST

www.firstline.co.uk

TECHNICAL INFORMATION