



# BULLETIN

---

## **Alfa Romeo 159 (Type 939) All models up to VIN 7097552**

### **ESP indicator lamp lights up Error code C1275 ABS solenoid valve**

If the error code listed above is discovered together with an illuminated ABS indicator lamp, this may be due to faulty software evaluation in the control unit.

First of all, check the power supply and the peripheral equipment of the ABS/ESP system. If all the test results correspond to the targets, the ABS/ESP control unit is the probable cause and should be replaced.

### **Repair note**

In some cases, it may be possible to update the software. If this is the case, please contact an authorized dealer.