Bulletin



© Hella KGaA Hueck & Co., Lippstadt 20 October 2006 1-1

Audi A2 All vehicles with 1.4 I engine

Alternator control lamp illuminates

If there are complaints about the above-mentioned fault, the cause could be the alternator regulator. Under certain circumstances, static charges may arise through the v-ribbed belt. This can give rise to erroneous illumination of the control lamp. In this case, the alternator regulator must be replaced (Hella no.: 5DR 009 728-001).



