## **Bulletin**



© Behr Hella Service GmbH, Schwäbisch Hall

01. Oktober 2005

1-1

## Audi A4 (Type: B5)

## Compressor failure through defect refrigerant lines

Vehicles with some engine types (e.g. TDI), the high and low pressure lines to the compressor run along a mounting brace on the compressor (see picture). As a result of touching the bottom engine plate (driving over rough ground). This can cause the refrigerant lines to become completely kinked or develop a leak. Through this the a/c system can fail completely. Please consider this in diagnosis of refrigerant loss on this vehicle.



## Bulletin

