Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 27. April 2006 1-1

Audi A4 (8D, B5) Model year: 1995 + 1996

Refrigerant loss / evaporator

If there are complaints about the cooling performance of the above-mentioned vehicles, the evaporator and the refrigerant quantity should be checked. The rubber brackets can lead to crevice corrosion at the corners of the evaporator. This can lead to the evaporator starting to leak.

In this case, the evaporator has to be replaced. The accumulator (filter-dryer) should be replaced at the same time. Suitable spare parts can be found in the *Behr Hella Service* range of parts.



