



Audi

A4, A5, Q5

Model year: March to May 2009

Engine: 2.0 TFSI

Loss of coolant

With the above-mentioned vehicles, a faulty coolant pre-feed pipe near the turbocharger can lead to a coolant leak.

The vehicle manufacturer has already taken up the problem during a recall campaign. For a variety of reasons not all vehicles may have been checked and/or repaired.

Within the context of the measure, the coolant pre-feed pipe is replaced and the implementation of the measure is documented in the service booklet.

Please bear this information in mind if complaints are made about loss of coolant and/or the coolant level warning light comes on.

Bulletin