© Hella KGaA Hueck & Co., Lippstadt

14th June 2006

Audi A6 (4B..) All models From model year 1997

Failure of the interior lighting and/or the electric window winders. Unlocking/locking of a door is sporadically not possible.

If there are complaints about the above-mentioned faults with these vehicles, one possible cause is the central locking control unit. Various relays are installed in this control unit. Faults in individual relays lead to the above-mentioned failures. To eliminate the fault, the central locking control unit must be replaced.





1-1