© Hella KGaA Hueck & Co., Lippstadt

23. Dezember 2002

Audi/VW with TDI Engines Loss of power and rough engine running.

Poor throttle response and loss of power due to porous turbo charger pressure tubes.

If poor throttle response, lack of power and rough running, are experienced with the above vehicles. The turbo charger pressure hoses could be the cause. Due to oil steam, weather influences and ageing, the hoses become porous and leads to a loss of pressure. In this case, remove the porous turbo charger pressure hoses, check for porous areas or cracking and replace if necessary.

It is recommended to read the fault code memory. A current fault code ,,,Turbo pressure incorrect" could indicate that the above failure has occured.

Bulletin





1-1