



BMW 5 Series (E39) Model year 03.2002 to 04.2002

Oil-level control lamp illuminates

If there are complaints from customers about the above-mentioned fault, the cause could be an incorrectly coded lighting-check module (LCM). Although the oil level is correct, the warning lamp illuminates after a drive (ignition off). With a few exceptions, this situation occurs only on vehicles with xenon light. In this case, the lighting-check module must be re-coded. Currently, this can be carried out only by the manufacturer.

Bulletin

