

\*\*\*

1-1

© Behr Hella Service GmbH, Schwäbisch Hall

01. Oktober 2005

## BMW E 36 build up to 12/95

## Roaring noises of the A/C

The cause of the above mentioned complaint, can be the expansion valve. The roaring noises occur between 2000-2500 rpm, with A/C running. These expansion valves, which were not damped, were installed until the end of '95. Damped valves have been installed since the beginning of '96.

The expansion valve needs to be exchanged to cure the problem.

Spare parts: 8 UW 351 239-261 or 8 UW 351 239-301

Please select the correct valve by referring to the catalogue details.



Bulletin

