



BMW

E36/7 (Z3), E38, E39, E46

Model year: 09.1999 to 10.1999

Engine: M52TU (2.0i + 2.3i + 2.8i)

Excessive engine temperature, coolant loss

In the case of the above-mentioned vehicles, a crack in the cylinder head can lead to coolant being lost, the engine temperature increasing and the message "Check coolant level" appearing in the instrument cluster. The coolant loss occurs in the area of the first cylinder, on the side of the exhaust manifold, in the area of the chain tensioner.

In the event of a complaint, if the diagnosis is clear, the cylinder head must be replaced.

Bulletin