

© Behr Hella Service GmbH, Schwäbisch Hall

01. Oktober 2005

BMW E39, E53 (5 Series, X5) Up to model year 6/2001 With manual air conditioning system (IHKR) Interior blower not working

The above-mentioned vehicles occasionally have the problem that after the ignition is switched on or after engine started, the interior blower no longer works. The problem only occurs when the rotary control for air distribution is in the "11 o'clock" position. Once this position is changed, the blower works again. This is a fault in the air conditioning control unit. This must be replaced in the event of a complaint.

Bulletin





1-1