



BMW E39 build year till 02/1996

Intermittent non function of the instrument cluster.

If, on this vehicle, the instrument cluster is functioning intermittently, a possible cause could be a faulty ground/earth connection. To rectify the problem the supply voltage and ground/earth connection should be checked. Mainly the fault is in the ground/earth point for the instrument cluster on the floor in the right front foot well (picture).

