



BMW E46 **build year 2/98 - 4/99**

Condense water in the footwell

On the above mentioned vehicles with climate control, it can occur, that condense water drips into the front passenger footwell when the a/c-system is running. This is due to a faulty routing of the condensation drain pipes therefore condensation isn't drained correctly. Remedy can be made here by a correction of the tube routing. It may be necessary to dismantle the evaporator unit for a better accessibility.



Bulletin