



BMW

All models with petrol engine up to model year 11 | 2002

Engine backfires and loses power, engine control lamp lights up.

If there are complaints with these vehicles that the engine misfires and is not running at full power and the engine control lamp lights up, one possible cause is a faulty ignition coil.

All vehicles with ignition coils from Bremi are affected. To eliminate the fault, all ignition coils with a date of manufacture before 11/2002 must be replaced.

The date of manufacture is printed on the top of the ignition coil. The four last figures show the calendar week and year of manufacture.

