



Citroen Berlingo All models with electric headlight range adjustment

Poor illumination of the road, poor headlight range

If there are complaints about the above-mentioned faults, it may be that the headlights are set too low. Due to the adjustment mechanism being too short, the headlights do not reach the desired cut-off line, despite being on the maximum setting. In this case, a special washer with a suitable retaining clip must be fitted on both sides between the lower headlight-fastening and the body. These parts can be obtained from the vehicle manufacturer.

Bulletin

