

© Hella KGaA Hueck & Co., Lippstadt

4 September 2007

Citroen C4 Picasso Model year from 10.2006

Headlight replacement

If, for example due to an accident, the headlight has to be replaced on the above-mentioned vehicle, it must be ensured that it is fitted correctly. The headlight is fastened with its lower mounting bracket (see illustration, Item A) into a plastic guide (see illustration, Item B). If too much force is exerted, this guide will be destroyed, and the headlight will lose its stability. For this reason, in the event of a repair, this plastic guide must be replaced as well. This guide is enclosed with the headlight.



