



## **Mercedes A-Class (W168) Models: 1997 - 2001**

### **Fogged windows**

If there are complaints about the above-mentioned fault, a possible cause could be water accumulating in the water channel.

The hose for draining rainwater running from the windscreen sits very tight in the bulkhead.

However, it is possible that the water could run along the outside of the hose and not through it, and that water accumulates in the water channel. This can be remedied by replacing the two drain hoses with a modified version. These have an integral rib which ensures that water outside the hose also drains away.

**Bulletin**