



Fiat Panda With 1.1 l (1108 ccm) MPI engine

Failure of the speed sensor.

If the fault complained about with these vehicles is that the speed sensor between the gear and the speedometer cable is faulty, one possible cause is water penetration. If the connection between the gear and the speedometer cable is separated, it must be ensured before these are connected again that the rubber seal in the screw connection of the speedometer cable is OK. If the seal is damaged or missing, water can penetrate and destroy the speed sensor.

