



## **Fiat Stilo** **All models**

### **Water penetrating the headlamp.**

If there are complaints about the formation of condensation in the headlamps, one possible cause is water penetrating the headlamp. In such cases, the complete headlamp(s) do(es) not have to be replaced. Only the rear cover has to be exchanged for a new modified version.

Even if the complaint only concerns one of the headlamps, the change should be carried out on both.



Cover for right-hand headlamp