



## Ford Escort, Build Year .01.95-10.97

Some vehicle in this build range experience total air conditioning loss. The problem is due to the electrical wiring of the compressor snagging the compressor belt.

### To rectify the problem:

1. Repair the electric wire to the compressor
2. Re-route the wire
3. Mount a routing clip to the radiator bracket
4. Check for operation

Regards

Your Service Partner Technical Team

Bulletin