



Ford

Focus (DAW, DBW, DNW, DFW)

Model year: 10.1998 to 13.01.1999

Heater noises

Whistling noises from the heater area may occur on the above-mentioned vehicles. One possible cause is a gap in the area of the heater box. This gap arises due to production tolerances. At blower level 3 and/or 4, the gap can cause whistling noises. To resolve the problem, various ventilation grilles and air ducts must be removed, and a special sealing strip must be attached in a certain area of the heater box. Please contact an authorized dealer in connection with this. Since 14th October 1999, an additional sealing strip has been stuck onto the heater housing at the factory.

Bulletin