



## **Ford Focus, build up to and including 15.01.99**

**Windscreen, Rearscreen and  
Sidescreens steam up. This is due to  
there being not enough ventilation in  
the area of the rear bumper.**

### **To rectify the problem:**

To rectify the problem Ford recommend to change the ventilator behind the rear bumper.

1. Remove the rear bumper
2. Remove the ventilation on the left and right side
3. Fit the replacement ventilator
4. Fit the rear bumper

Regards

Your Service Partner Technical Team

Bulletin