



Ford

KA, Puma

Fiesta with petrol engine, model year 1996 - 2002

Escort, model year 1991 - 1999

Galaxy with DOHC-engine, model year up to 07.1997

Mondeo, model year 1993 - 1999

With air-conditioning and Visteon FS10 compressor

Compressor noise /

Failure of the air-conditioning

Should the air-conditioning fail in the above-mentioned vehicles (compressor's magnetic clutch does not switch on) or the compressor is noisy, this is often due to a faulty driver/pulley or magnetic clutch. To eliminate the cause, the whole compressor does not always have to be replaced. Quite often, it is sufficient to replace the magnetic coil and/or the driver/pulley. First, though, make sure that the compressor oil has not already been "burnt" through overheating, or that the compressor has not been damaged in any other way (leak, abrasion).



BEHR HELLA
SERVICE

Bulletin