



## Ford Mondeo, Build year 08.93 – 03.98

Some vehicle in the build range can experience water ingress in the front right hand foot well. This is due to defective seal between the pollen filter air ducting and the mounting.

### To rectify the problem:

The cause of the problem is a faulty seal, which must be replaced by a new one.

1. Remove the pollen filter
2. Remove the air ducting
3. Renew the seal
4. Refit components in reverse order

Regards

Your Service Partner Technical Team

Bulletin