



Ford

Mondeo

Model year: until 04.1996

Engine: 1.8L turbo-diesel

Loss of coolant

In the case of the above-mentioned vehicles, complaints with regard to loss of coolant may arise. The cause may be a damaged coolant hose. This hose is very close to the turbocharger housing and can wear through. As a corrective action, modified coolant hoses and fastening elements are available from the vehicle manufacturer. Please contact an authorized dealer. Vehicles produced from May 1996 were modified by the factory.

Bulletin