



Ford Transit Model 2000 With fog lamps

Water in the fog lamps.

If there are complaints with these vehicles that water or humidity penetrates the housing and can be found in the fog lamp after the vehicle has driven through puddles, one possible cause is the lack of drain hole in the rear cover of the fog lamps.

To eliminate the fault, a modified cover must be installed.

This has an additional hole that allows water that has penetrated to escape.