



## ***Honda Civic***

***Model year from 02.2001 to 12.2006***

***All vehicles***

### **Noises from the headlights**

If there are complaints about the above-mentioned fault, the cause could be a defective headlight range adjustment servomotor. If the motor is defective, this condition can be detected via a buzzing noise when the ignition is switched on. In some cases, cracking or rattling noises may also occur. It is then necessary to replace the servomotor.

**Bulletin**

