



# BULLETIN

---

## **Mazda 6 (GG/GY) Model year: 2002 - 2008 Engine: 2.0 Di**

### **Compressor malfunction**

If the compressor in one of the vehicles mentioned above malfunctions, the power supply to the magnetic clutch should be checked.

The electrical cable for the magnetic clutch power supply (+) is routed to the compressor through the engine block area.

Water leaking into the connector housing (figure) can cause corrosion to form. This can lead to contact problems or a power failure.

In order to remedy this issue, the damaged electrical connection should be renewed.

