



Mercedes E-Klasse *Man. year: till beginning 1997*

Failure of the sidelight halogen lamps

Voltage spikes in the onboard power supply can burn out the sensitive halogen sidelight bulbs. This happens particularly when starting with the lights switched on. Please inform your customers not to start the engine when the lights are switched on.

