



Mercedes Benz W 202 **Built between 01.06.1993 – 31.12.1995**

Engine can misfire or cut out during driving

If there are complaints about the above-mentioned fault, the overvoltage protection relay K1/2 could be the cause.

A soldering fault in the relay gives rise to these complaints.

The above problems occur sporadically and no faults are stored.

If the engine cuts out it could be that it can be started up again after a brief pause. In this case the relay should be replaced.