



BULLETIN

Mitsubishi/Fuso Canter TF/TF1 Model year: 2011-09-16 - 2014-12-17

Oil cooler hose

On the above vehicles, the oil cooler hoses on the fully automatic direct shift transmission (Duonic transmission) must be checked and, if necessary, replaced. If this is not done, there is a risk of the hoses bursting and oil escaping.

Further information can be obtained from the vehicle manufacturer. When contacting the manufacturer, provide the operation reference code: RC1502