



Opel Astra G with 1.6 litre 74 KW engine (X16XEL)

No cooling performance despite A/C lamp lighting up

In the case of vehicles with a manual air conditioning system, the situation may arise that there is no change in temperature after the air conditioning system has been switched on and the pilot light has illuminated. In this case, the amount of refrigerant in the system and, in particular, the evaporator temperature sensor should be checked. If the sensor is faulty, the voltage supply to the compressor is interrupted.

Bulletin