



Opel **Astra G build year 1998+1999** **Zafira build year 1999**

Misted window due to a faulty recirculation flap motor

On the above-mentioned vehicles (with manual a/c) a misting of the window(s) can occur. If this fault occurs, the function of the recirculation flap, the recirculation flap motor and the switch should be checked. The function can be checked by manually pressing the recirculation switch and listening for the motor and watching the flap move. If the motor can not be heard, a faulty recirculation flap motor and/or a faulty switch can be the cause .

Bulletin