



## **OPEL**

### **Astra-H, Zafira-B, Vectra-C, Signum, Motor code Z19DTH, Z19DTJ, Z19DTL**

**All vehicles with Bosch generator from year of manufacture 2007**

### **Noises on the area of the V-ribbed belt Battery discharge**

**Problem:**

Intensive noise development in the area of the Poly-V belt with simultaneous battery discharge possible.

**Possible cause:**

incorrectly functioning generator freewheeling pulley.

**Solution of the problem:**

Check the freewheeling pulley and renew if necessary.

A special tool (KM-6372) is required to replace the generator freewheeling pulley.

