BULLETIN



Vauxhall Astra J Model year: 2010 - 2012

Risk of fire due to blocked radiator fan

On the vehicles mentioned above, the battery cover can come loose, get into the radiator fan and block it. This can result in noises from the engine compartment and an elevated engine temperature. There is a risk of fire due to various components overheating.

To eliminate this problem, the first step is to remove the battery cover. Make sure that the positive pole remains protected/covered.

An adapter wiring harness can be fitted as an additional measure. For more information, see the "Opel Astra J, radiator fan module" bulletin.

Even though the owners of the affected models have been informed, it can be assumed for various reasons that not all vehicles have been fully repaired.

Page 1 of 1

© HELLA KGaA Hueck & Co., Lippstadt

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.

