



Opel Corsa B From model year 1995 With engine code X12SZ

No lambda control

With Opel Corsa B models with the engine code X12SZ from model year 1995, the lambda control can intermit.

A fault memory read-out shows that a fault has not been entered in the fault memory.

The cause of the problem can be insufficient dimensioning of the ground cable on the cylinder head.

For this reason the central ground connection at the cylinder head should be checked and the ground cable renewed if necessary.

Bulletin