

1-1


© Hella KGaA Hueck & Co., Lippstadt

24. Juni 2003

Opel Corsa-C Buildyear 2001-2002 All models

Water ingress in the left front foot well.

If, on this vehicle water gets into the left front foot well, a possible cause could be a loose cover of the relay box. To rectify the problem the screws of the relay box cover must be tighten.



Relay box cover

