



Bulletin

Opel Meriva B Model year: 2010 - 2012 With air-conditioning system

Loss of oil from the compressor / Loss of refrigerant

The above-mentioned vehicles can experience a compressor leakage. This is mostly noticeable by escaping oil/dye. To fix this problem, the compressor must be exchanged for a modified version:

Old Part No:	Replaced By New Part No:
13 271 264	13 395 696
13 271 266	13 395 693
13 271 267	13 395 694
13 271 268	13 395 695
13 271 269	13 395 696

Vehicles from the 2012 model year onwards, i.e. from chassis number B4408747, use factory modified compressors.

The compressors of Behr Hella Service are modified without exception and show no trace of the above-mentioned problem. In the table on the right OE part numbers are set out next to BHS numbers for purposes of comparison.

	Original Part No.	BHS Part No.
<i>GM</i>	13395696	8FK 351 340-241
<i>GM</i>	13395694	8FK 351 340-251
<i>GM</i>	13395696	8FK 351 340-271
<i>GM</i>	13395695	8FK 351 340-361
<i>GM</i>	13395693	8FK 351 340-371
<i>Opel</i>	1618425	8FK 351 340-241
<i>Opel</i>	1618423	8FK 351 340-251
<i>Opel</i>	1618425	8FK 351 340-271
<i>Opel</i>	1618424	8FK 351 340-361
<i>Opel</i>	1618425	8FK 351 340-241
<i>Opel</i>	1618422	8FK 351 340-371
<i>Vauxhall</i>	13395696	8FK 351 340-241
<i>Vauxhall</i>	13395694	8FK 351 340-251
<i>Vauxhall</i>	13395696	8FK 351 340-271
<i>Vauxhall</i>	13395695	8FK 351 340-361
<i>Vauxhall</i>	13395696	8FK 351 340-241
<i>Vauxhall</i>	13395693	8FK 351 340-371