



# BULLETIN

---

## **PEUGEOT** **Model: 307** **All models with ABS/ESP**

### **ABS warning light illuminates**

**Error code: 21287**

### **Left rear RPM sensor**

If the above error is discovered together with an illuminated ABS warning light, this may be due to a cable fracture underneath the heat shield cover for the rear muffler. In this case, the wiring harness must be checked and repaired if necessary.