



Peugeot 307 **All models with 2.0 HDI engine**

Poor engine start-up, starter speed too low.

If there are complaints with these vehicles that engine start-up is poor and the starter speed is very low, this could be caused by the starter being too weak. In this case, the nominal power of the starter is too low.

A modified, more powerful starter has to be installed to eliminate the fault. Suitable replacement parts can be found in Hella's "Starter and Alternator Replacement Parts" catalogue.

Bulletin

