



Renault

Espace IV (JK0); Vel Satis

Model year: 2002 – 2004

With engine: P9X 701 (3.0 dCi)

Inadequate cooling performance of the air conditioning system

If there should be complaints with the above-mentioned vehicles about poor cooling performance in town traffic, this can be related to the software status of the injection system control unit. When the engine is at operating temperature the compressor is switched off in cycles by the injection system control unit. A fault code is not usually stored. The problem can be remedied by reprogramming the control units listed below.

Vehicle	*Part no. of the control unit before reprogramming
Espace IV	82 00 209 001
	82 00 234 826
	82 00 243 877
	82 00 248 723
	82 00 264 013
	82 00 287 269
	82 00 312 426
	82 00 312 428
	82 00 413 308
82 00 450 087	
Vel Satis	82 00 050 937
	82 00 139 092
	82 00 139 102
	82 00 208 997
	82 00 394 162

* Part no. can be determined by the diagnosis unit

Bulletin