



Saab 9-5 With B205E (150 PS) or B235E (170 PS) engine

Long engine start-up time.

If there are complaints with these vehicles about a long starting time before the engine start, one possible cause could be the spark plugs.

In the case of complaints, or when servicing is being carried out, the spark plugs should be replaced with the following type: BCPR6ES.

This type of spark plug shortens the starting time.