



Skoda Fabia Engine code AUB Model year 2000–2004

Judder when accelerating in the range from approx. 1,800 1/min

If there are customer complaints about the above-mentioned problem, possibly also with increasing judder under harder acceleration, checking the fault memory may not offer a solution, as no fault code is stored.

Here, a defective ignition coil may be the cause, and in this case, the solution is to replace it.

Bulletin