



Skoda Octavia 1.8 T Model year 2001-2003

Engine runs poorly, judders when setting off, and gives poor performance

If the above complaints are received, a defective ignition coil could be the cause. This fault can result in one cylinder failing, which can be detected by the illumination of the engine warning light. In such cases, the ignition coil must be replaced.

Bulletin

